

OKUMA

IGF LATHE

TRAINING MANUAL

Ellison Technologies – 9912 S. Pioneer Blvd, Santa Fe Springs, CA 90670

.

DESCRIPTION

SHEET	
-------	--

INTRODUCTION	1
FEATURES	1
OUTLINE	3
DEFINITIONS	3
DATA SETTING PROCEDURES	4
SAMPLE PART	5
IGF PROCEDURE FOR TOOL DATA ENTRY (STEP ONE)	6
(STEP TWO) - FOR FOUR-AXIS MACHINES ONLY	7
(STEP TWO) - FOR TWO-AXIS MACHINES ONLY	. 8
DATA NO. SCREEN	9
TOOL CODE SCREEN	10
DATA SETTING SCREEN	12
CHECK OF DATA NO, SCREEN FOR FIRST TOOL	16
SHORT VERSION TO ENTER TOOL TWO	17
SHORT VERSION TO ENTER TOOL THREE	18
SHORT VERSION TO ENTER TOOL FOUR	· 19
SHORT VERSION TO ENTER TOOL FIVE	20
SHORT VERSION TO ENTER TOOL SIX	21
CHECK OF DATA NO. PAGE FOR COMPLETED INPUT	22
IGF PROCEDURE FOR MATERIAL DATA ENTRY	23
STEP ONE - IGF STARTUP	24
STEP TWO - MATERIAL TABLE (ASSIGN NUMBER)	25
STEP THREE - MATERIAL TABLE (ASSIGN NAME)	26
STEP FOUR - ROUGH COPY TURNING PAGE	27
STEP FIVE - FINISHING PAGE	31
STEP SIX - THREAD CUTTING PAGE	34
STEP SEVEN - TAPPING PAGE	39
STEP EIGHT - GROOVING PAGE	41
STEP NINE - GROOVE FINISHING PAGE	46
STEP TEN - DRILLING(HSS) PAGE	49
STEP ELEVEN - DRILLING(CARBIDE) PAGE	54
STEP TWELVE - DRILLING(CENTERING) PAGE	59
STEP THIRTEEN - CENTERING PAGE	61
STEP FOURTEEN - RECESSING PAGE	63

Introduction:

The Interactive Graphic Function (IGF), has been developed as an extension of the OKUMA OSP control. IGF allows programming at the OSP control, through a set of interactive operations with the N/C. The operator can program parts with complicated or simple contours, by keying-in responses to the prompts displayed on the controls CRT screen.

Features :

1) Completed programs can be checked, using the animated display.



- 2) Control generated, computer assist programming for 4-axis machining, and editing of 4-axis simultaneous programs.
- 3) Automatic selection of machining conditions and cutting tools.
- 4) Background programming, machine can be cutting a piece part while control is being used to prepare another part program.



Machining of one piece part.

Features : (continued)

5) Effortless editing of machining order and conditions.



6) Simplified shape definition.



7) Input data is saved on a large capacity bubble memory.

Standard : Capacity equivalent to 60 meters (197 feet) tape length

Optional : OSP5000L-G ... Capacity equivalent to 10,240 meters (33,600 feet) tape length OSP500L-G ... Capacity equivalent to 3,840 meters (12,600 feet) tape length

8) Existing programs, stored in menory, that were not prepared using IGF may be exceuted or run, as well as programs prepared using IGF.





Machined Part

Programs prepared with IGF or without IGF, may be run

IGF Outline :

IGF executes the graphic display of the machining status, when the data for, tooling, material condition, parameters and shape are entered using the graphic editing functions. The data from the machining order and cutting conditions is then converted into a NC program after verification and editing.

Tool data, material data and parameters are automatically called, when the entry of them is required during the programming of a part. This data is entered, by responding to the guides (guide drawings and messages), displayed on the control CRT. The data is then transferred into the NC part program. The data (tool, material and parameter) can be separately entered and registered.

Definitions :

Tool data	: Is all data related to tools, such as, tool type, tool shape, turret number, etc.
Material data	: Part material can be identified and stored, con- sisting of; data for Constant Surface Footage, depth of cut and feedrate.
Parameters	: This refers to data that is a requisite for NC program generation. The data includes :
	 Standard tailstock center dimensions Chuck barrier geometry
	- Upper and lower turret KPM's limit
	- Nominal diameter for threading
IGF data	: This refers to the data entered using the graphic editing function, such as, blank shape, cutting conditions, tools, work shape and parameters.

NOTE :

IGF data, prepared using the IGF function, can be stored on floppy disk media storage. This should be done to insure sufficient control storage memory or to provide back-up and protection to on-going work.

This IGF data, however, cannot be used with OSP controls that do not have the feature of IGF programming. The correctness of the program data, on these controls, cannot be guaranteed. Data Setting Procedures :

Tool, material and parameter data are factory set by OKUMA, for general turning operations. They can, however, be edited, as needed, to reflect the USER'S knowledge of machining for their product line.

Tool data :

Cutting tools used for a specific part, can be registered (or input) prior to begining the IGF programming session. The IGF system allows the USER to register (or define) the tool data for up to 104 different tools. OKUMA provides the data for 13 standard tools with the system.

The tool data consists of three parameters, they are ;

DATA NO., TOOL CODE, and TOOL FORM CODE

1) DATA NO. (NO)

This page, in the control, allows the programmer to identify up to 104 individual tools. A further restriction, is that only 38 tools may be assigned to the upper turret (A), at one time and a like number may be assigned to the lower turret (B), at the same time.

2) TOOL CODE (CD)

At this page, in the control, the programmer must select (from the DATA NO. page), tools that match the cutting type needed and the correct cutting direction. The IGF system allows 38 combinations of these parameters and one code number is assigned to one tool number.

3) TOOL FORM CODE (FC)

The IGF system now displays a page, showing several possible tools, in accordance with the previously entered TOOL CODE. The operator/ programmer has to select the correct tool to use, based on the intended cutting, mounting direction of the tool and the tool shape. Only one tool number can be assigned to one tool form code number.



The above sample part would require six cutting tools, they are :



Tool number two - 80 degree diamond x .015 nose radius Finish O/D of part

Tool number three - Centerdrill

Tool number four - .750 dia. drill - thru

Tool number five - 80 degree diamond x .031 nose radius Rough I/D of part.







IGF Procedure for Tool Data Entry :

Step One

From the normal machine operation mode, press the EDIT AUX key [PTAUX], then press the function key [PT], the CRT should display the IGF start-up page.

বা

PROG OPERATION IGF **OKUMA IGF** = IGF Key in the file name and press the WRITE key (when using the graphic edit restart, key in '*' as a file name) GRAPHIC PROGRAM TOOL MATE-IGF IGF PARA-MAKE DATA RIAL CONVERT guit EDIT METER F1 **F8** F2 F3 F4 F5 **F6** R) F4 1104State alasi 10 Control

At any time the IGF session, for Tool Data Entry, may be terminated by

pressing function key

There will be no loss of input data.

F7

.

Step Two - For Four-axis machines only

From the Function keys, located at botton of the CRT, select

TOOL DATA

Now select which turret, by selecting one of the TURRET SELECTION KEYS,



A for upper turret,



B for lower turret.

The CRT screen display should be as shown below, if turret A was selected.

PI	rog opei	RATION	GF	TOOL DA	TA		
	T	URF A	let - Tu	SE] [RR]	LEC1 ET	Γ	
= IGF > TF !							
ORDER	ORDER					guit	
F1	F2	(F3)	F4	F5	F6	F7	F8



From the tooling information, given on page 5, let's enter the first tool.

From the Function keys, select

F 3

TOOL DATA.

The CRT screen should be as displayed below.

PROG OPERATION IGF		TOOL DA	TA		
DATA NO.				1 in	
	NO	** TOO	L DATA	TABLE **	F
DATA NO =		CONTEM.	19		
	3				
	4. K				
	6				
	7				
	8				
	10 10				
	11				
	12				
	13				
(When using graphic edit real > TF	start, k	ey in '*' as	a file na	me)	
Tool data NO. ?					
1			~~~~~	·	
				01777	
ORDER _				guir	
F1 F2 F3	F4	F5	F6	F7	F8

To establish our first tool, we must do the following :

From the TOOL DATA TABLE select tool NO. 1, press

from the ten

1

key pad and then press

WRITE

To verify the input, check the highlight area on this page, it should look like this:

Step Two - (continued)

Within the TOOL DATA TABLE, up to 104 tools can be registered for the upper A turret. For machines with two turrets (Four-axis) up to 38 tools can be registered for the lower B turret.

To view the multiple pages of the TOOL DATA TABLE, use the page up button or the P page down button. Pressing the P page down button, several times, will yield the CRT screen display shown below. To return to the first page, press the page down button once.

(PROG	OPERATI	ON IGF		TOOL DA	TA		
++DAT	A NO.**				1	l in	
				** TOO	L DATA (TABLE **	
			NO	CONTEN	rs	TOOL SI2)E
DATA	NO =		92				
			93				
			94				
			95				
			90				
			97				•
			00				
			100				
			101				
			102				
			103				
			104				
(When u > TF Tool dat !	sing grapi a NO. ?	nic edit r	estart, ko	y in '*' as	a file nan	1C)	
	order 🛔					guit	
F1	F2	F3	F4	F5	F6	F7	F8

(9)

Step Three

From the Function keys, select



ORDER \downarrow , for the next page of TOOL

DATA ENTRY. The CRT screen should be as displayed below.

PROG OPERATION IGF TOOL DATA **TOOL CODE** 1 in ** TOOL CODE TABLE ** +1() CODE CODE (1)ROUGH OD -(14)THREAD ID ---CODE CD = [CONTRACTOR(2)ROUGH ID 🕶 (15)THREAD FACE (3)ROUGH FACE (16)THREAD OD ---(17)THREAD ID -4)ROUGH OD ---5)ROUGH ID 🛥 (18)THREAD FACE | 6)ROUGH FACE (19)GROOVE OD 7)FINISH OD -(20)GROOVE ID 8)FINISH ID 🕶 (21)GROOVE FACE -(9)FINISH FACE | (22)DRILL HSS (23)DRILL CARBIDE (10)FINISH OD ---(11)FINISH ID -(24)CENTER DRILL (12)FINISH FACE (25)RECESS OD 🖌 (13)THREAD OD ----(26)RECESS ID 🔪 Tool data NO. ? IOF TOOL CODE? 1 guit ORDER ORDER **F1** F3 F4 F5F6 **F7 F8 R** 2 A tool must now be selected, from page 5 we know the shape and that the tool is to rough the O/D of the part.

From the TOOL CODE TABLE select tool NO. 1, press

WRITE



from the ten

key pad and then press

ì

To verify the input, check the highlight area on this page, it should look like this :

Within the TOOL CODE TABLE are 38 tools, classified by, the particular tools cutting type and direction of cutting. One tool code is assigned to one cutting type and direction.

To view the two pages of the TOOL CODE TABLE, use the p page up button or the p page down button. Pressing the p page down button, one time, will yield the CRT screen display shown below. To return to the first page, of the TOOL CODE TABLE, press the page up button once.

PROG OPERATION IGF **TOOL CODE** * 1 ()	TOOL DATA 1 in ** TOOL CODE TABLE ** * CODE (27)MDRUL +
CODE CD = [Stationard	(28)MDRILL - (29)BORING \neq (30)BORING - (31)TAP \ddagger (32)TAP - (33)REAMER \ddagger (34)REAMER - (35)END MILL \ddagger (36)END MILL - (37)FACE MILL \ddagger (38)FACE MILL -
Tool data NO. ? !OF TOOL CODE ? !	
	дит
F1 F2 F3	F4 F5 F6 F7 F8

Step Four

From the Function keys, select



DATA ENTRY. The CRT screen should be as displayed below.



The DATA SETTING page appears, with the "highlight" area at TOOL NO. (TN). Our first tool is located in turret position one, using tool offset one. To enter the tool or turret number :

Press



WRITE

.

.

The COMMAND DATA area now looks like this :

1

COMMAND DATA

TOOL NO. TH OFFSET NO. ON

The "highlight" cursor area, automatically drops down to the OFFSET NO. (ON) data entry area. To enter the tool offset number :



The COMMAND DATA area should now look like this :

COMMAND DATA TOOL NO. TN= 1 OFFSET NO. ON=

Step Four - (continued)

The COMMAND DATA area is now completed, it should appear on the CRT screen as shown below.



The "highlight" area is now at FORM CODE NO. (FC). From the right hand side of the screen, graphics area, one of the three displayed tools must be chosen, that matches our tooling needs. The first tool should be our choice, to enter :



Entering the remainder of the TOOL EDGE DATA, would be as follows :



The EDGE TOOL DATA area should now look like this :

TOOL EDGE DATA	FORM CODE NO.	FC=	1
	TOOL ANGLE	A1=	80.0000
	EDGE ANGLE	A2=	5.0000
	STICKING OUT	L =	2.0000

Step Four - (continued)

The COMMAND DATA and TOOL EDGE DATA areas are now completed, they should appear on the CRT screen as shown below.



The "highlight" area is now at INDEX POSIT. (XT). This value and the (ZT) value, should be input as the "soft" limits used for tool change.

To enter the values, the following steps must be taken, they are :



The TOOL INDEX area should now look like this :

```
TOOL INDEX
```

XT= 20.0000 ZT= 20.0000

INDEX POSIT.

Completed entries of all data for tool number one.

With the COMMAMD DATA, TOOL EDGE DATA and the TOOL INDEX areas of the DATA SETTING screen now complete, the CRT screen should be as displayed below.



2

To check our work we must return to the first page of the TOOL DATA section or to the DATA NO. page

From the Function keys (bottom of CRT screen) select and press twice.

If we compare this current page to page number eight, of this book, note that the TOOL DATA TABLE reflects what kind of tool we created, listed under (CONTENTS) and the current TOOL SIZE , listed under the columm for TOOL SIZE.

ORDER **A**

F1

PROG OPERATION IGF	TOOL DATA	
DATA NO.		1 in
	** TOOL DATA	TABLE **
	NO · CONTENTS	TOOL SIZE
$\mathbf{DATA} \mathbf{NO} = \mathbf{\underline{CONSCRAMENT}}$	I ROUGH OD -	80.0000
	2 Q	
	4	
	5	
	6	
	7	
	8	*
	9	
	11	
	12	
	13	
LOB		
tool data NO 2		
toor unta NO. 1		
		QUIT
	<u> </u>	
	\neg \frown \frown	
F2 F3	F4 F5 F6	F7 F8

(16)

Without showing all the steps, screen by screen, to input the second tool from page five, let's enter the values working from this format,



(17)

Without showing all the steps, screen by screen, to input the third tool from page five, let's enter the values working from this format,



Without showing all the steps, screen by screen, to input the fourth tool from page five, let's enter the values working from this format,



(19)

Without showing all the steps, screen by screen, to input the fifth tool from page five, let's enter the values working from this format.



Without showing all the steps, screen by screen, to input the fifth tool from page five, let's enter the values working from this format.



(21)

To check our completed input we must return to the first page of the TOOL DATA section or to the DATA NO. page

ORDER **A**

From the Function keys (bottom of CRT screen) select and press twice.

If we compare this current page to page number sixteen, of this book, note that the TOOL DATA TABLE reflects what kinds of tool we created, listed under (CONTENTS) and the current TOOL SIZE, listed under the columm for TOOL SIZE, for all the identified tools needed for our sample part.

PROG **DA1	OPERATI A NO.**	NO	TOOL DA	TA L DATA	1 in TABLE **	F	
DATA	. NO =		NO 1 2 3 4 5 6 7 8 9 10 11 12 13	CONTEN ROUGH FINISH CENTEF DRILL C ROUGH FINISH	OD - OD - DRILL ARBIDE ID - ID -	80.000 80.000 80.000 80.000 80.000	
tool co ! OB tool da !	ode ? Ata NO. ?	~	·				
	order 🖌					guit	
F1	F2	F3	F4	F5	F6	FZ	F8

When we have completed all our inputs for TOOL DATA, we can exit this

section by pressing operation mode.

function key and return to normal machine

F7

Material data :

Material cutting conditions, used for a specific part, can be registered (or input) individually prior to begining the IGF programming session. The IGF system allows the USER to register (or define) the material cutting conditions (feed, speed, depth of cut) for 13 different types of material. This allows the user to capture and re-use specific material cutting knowledge, based on the users own product knowledge.

The material data consists of three parameters, they are ;

NAME NO., MATERIAL NAME, CUTTING CONDITIONS

1) NAME NO.

This page, in the control, allows the programmer to assign up to 13 individual material numbers. From these numbers the control is able to select the proper cutting values for the required material.

2) MATERIAL NAME

At this page, in the control, the programmer must now assign the material name, which the control stores against the selected material number, defined in step number one. The material name can be up to eight alpha-numeric characters in length, provided that the first character is an alpha.

EXAMPLE : Material is to be 303 Stainless Stell

INPUT : SS303

3) CUTTING CONDITIONS

The IGF system now expects the programmer to input values for feed, speed and depth of cut, for several types of cutting conditions, eleven types to be exact. They are stored against the assigned material number and name. They are :

> ROUGH COPY TURNING FINISHING THREAD CUTTING THREAD TAPPING GROOVING GROOVE FINISHING DRILLING (HSS) DRILLING (CARBIDE) DRILLING (CENTERING) CENTERING RECESSING

> > (23)

IGF Procedure for Material Data Entry :

Step One

From the normal machine operation mode, press the EDIT AUX key then press the function key \mathbf{r}_{77} , the CRT should display the IGF start-up page.

Q

PI	ROG OPER	RATION I	GF				
		OK	UM	A I	GF		
= IGF Key in th (when u	te file name sing the gra	and press phic edit :	the WRIT	E key y in '*' as a	a file name)	
GRAPHIC EDIT	PROGRAM MAKE	TOOL DATA	MATE- RIAL	PARA- METER	IGF CONVERT	igf guit	
F1	F2	F3	F4	F5	F6	FZ	F8

At any time the IGF session, for Material Data Entry, may be terminated by

pressing function key



. There will be no loss of input data.

Step Two

For our sample part, on page 5, we can enter the material specifications in this section. The material is, FREE MACHINING STAINLESS STEEL WROUGHT, (austenitic) 303, bhn 135 - 185 annealed. To start entering the material data, press function key FA. . The CRT screen should be as displayed below.

PROG	OPERATI	ON IGF		MA	T. DATA		
- 1 -			NO	** MAT NAME	ERIAL TA	BLE **	
NAME	NO =		1 2				
			3 4				
			5 6 7				
			· 8				
			10 11				
			12 13				
(When u > MF materia !	ising grapi I name N	nic edit r O. ?	estart, ke	y in '*' as	a file nan	ne)	
	order 🛔					guit	
F1	F2	F3	F4	F5	F6	F7	F8

To establish our first material, we must do the following : From the MATERIAL TABLE select material NO. 1, press 1 key pad and then press write .

To verify the input, check the highlight area on this page, it should look like this :

from the ten

(25)

Step Three

At step two we gave the material a number. To advance the control to the next screen (step three), we must press $\mathbf{F2}$ order $\mathbf{\downarrow}$, the CRT screen should be as displayed below. This screen allows us to give a formal name to the material, the name can be eight characters long and must start with an alpha.

PROG OPERATION IGF	MAT. DATA
- 2 - NO. 1=	** MATERIAL TABLE **
NAME NA =	8
	material name within 8 alphanumerical
	characters can be keyed in.
	-
! OB material name NO. ? ! OF !	
	дит
F1F2F3	F4 F5 F6 F7 F8

Our material is Stainless Steel - 303, which we will input as : SS303 To input the material, we must use the alpha character keyboard and the ten key pad. The entries would be :



To verify the input, check the highlight area on this page, it should look this : [55303....]

Step Four

At step three we defined the material type, based against an assigned number, to the control. To advance the control to the next screen (step four), we must press $\mathbf{F2}$ order \downarrow , the CRT screen should be as displayed below. This screen allow us to input constant surface footage, feedrate and depth of cut for six different types of cutting conditions.

Definitions of screen variables :

VR = Constant Surface Footage

FR = Feedrate (expressed as IPR)

DX = Depth of cut, expressed as diameter value

No decimal points are allowed on this page, so a .2000 depth of cut per side, must be input as 4000

PROG OPERATION - 3 - NO. 1= SS303 CUT. DIRECTION OD TURNING ID TURNING FACING FACING FACING FACING OF OF	IGF CUT. SPE VR= VR= VR= VR=	MAT DUGH COP ED FEE 0 FR= 0 FR= 0 FR=	TURNIN TURNIN DRATE O O O	0.000 G* CUT DF DX= DX= DX=	1 in SPTH 0 0 0
order 🛉 order ↓				дит	
F1 F2 F	r3 F4	F5	F6	F7	F8

Step Four - (continued)

To input the values for CUT. SPEED, the following steps must be taken, they are :



Step Four - (continued)

The cursor must now be returned to the top of the CUT. SPEED columm for entering of the values. This is accomplished by pressing the up cursor 1 arrow three times and the right cursor arrow once.

For DX



Step Four - (continued)

Upon completion of the inputs, from page 28 & 29, the CRT screen should be as displayed below.

PROG OPERATION IC - 3 - NO. 1= SS303 CUT. DIRECTION OD TURNING ID TURNING FACING i FACING i FACING j Material name NO. ? ! OF ! OF !	*ROUGH CUT. SPEED VR= 600 VR= 600 VR= 400 VR= 400 VR= 400	MAT. DATA COPY TURNI FEEDRATE FR= 150 FR= 150 FR= 100 FR= 100	0.0001 in NG* CUT DEPTH DX= 3000 DX= 3000 DX= 1000 DX=
order 🛉 order 🗼			guit
F1 F2 F3	F4 F	5 F 6	F7F8

Step Five

At step four we defined values for the CUTTING DIRECTION to accommodate,

speed, feed and depth of cut for ROUGH COPY TURNING. To advance the control

to the next screen (step five), we must press

screen should be as displayed below.

ORDER _ €ġ•

, the CRT

This screen allows us to input values for FINISH constant surface footage, X and Z-axis Finish stock allowance and up to four choices of FINISH feedrate.

> No decimal points are allowed on this page, so a decimal value of .0020, must be input as 20

PROG OPERATION - 4 - NO. 1= SS303 CUTTING SPEED FINISHING STOCK	N IGF •FIN X-AXIS	MAT. DA ISHING*	TA 0.00 VX=	01 in
FINISHING STOCE FINISH V FINISH VV FINISH VVV FINISH VVV	Z-AXIS (ROUGH) FEE (SEMI-FINISH) (FINISH) FEE (FINE FINISH)	DRATE) FEEDRATE DRATE) FEEDRATE	LZ= F1= F2= F3= F4=	000000
! OF ! OF ! OF				
order 🛉 order ↓			guit	
F1F2	F3 F4	F5 F	6 F 7	F8

Step Five - (continued)

To input the values for VF, LX, LZ, F1, F2, F3 and F4, the following steps must be taken, they are :

For VF	press	700 and WRITE, then cursor down
For LX	press	1 0 and WRITE, then cursor down
For LZ	press	2 0 and WRITE , then cursor down
<u>For F1</u>	press	70 and WRITE, then cursor down
For F2	press	4 0 and WRITE , then cursor down
For F3	press	3 5 and WRITE, then cursor down
For F4	press	2 0 and WRITE

Step Five - (continued)

÷,

Upon completion of the inputs, from page 32, the CRT screen should be as displayed below.

PROG OPERATION IGF MAT. DATA - 4 -0.0001 in NO. 1= SS303 *FINISHING* **CUTTING SPEED** VF= 700 FINISHING STOCK X-AXIS LX= 100 FINISHING STOCK Z-AXIS LZ= 20 FINISH V (ROUGH) FEEDRATE F1= 70 FINISH **V V** (SEMI-FINISH) FEEDRATE F2=40 FINISH VVV (FINISH) FEEDRATE F3= 35 FINISH VVV (FINE FINISH) FEEDRATE F4= 20202 ! OF 1 OF I OF 1 guit ORDER 4 ORDER F1 F5F6 F2F3 F4F7**F8**
Step Six

At step five we defined values for FINISHING to accommodate, finish constant surface footage, finish stock allowance and four finish feedrates. To advance the control to the next screen (step six), we must press $\mathbb{F2}$ order \downarrow , the CRT screen should be as displayed below.

This screen allows us to input values for THREADING, which include values for constant surface footage, depth of cut and stock allowance for "spring" or semi-finish pass.

> No decimal points are allowed on this page, so a decimal value of .0020, must be input as 20

- V = Constant Surface Footage
- **D** = Depth of cut (first pass)
- L = Finish stock allowance

PROG OPERATION IGF		MAT. DATA	
- 5 -			0.0001 in
NO. 1= SS303	*THREAD	CUTTING*	
THREADS PER INCH	CUT. SPEED	CUT DEPTH	FIN. STOCK
OVER 24	v - Exercise	1 D = 0	τ
OVER 16	$\mathbf{V} = 0$	D = 0	L = 0
OVER 12	$\vec{v} = \vec{0}$	$\vec{D} = \vec{0}$	$\mathbf{L} = 0$
OVER 10	$\mathbf{V} = 0$	$\mathbf{D} = 0$	$\mathbf{L} = 0$
OVER 8	V = 0	D= 0	$\mathbf{L} = 0$
OVER 6	$\mathbf{V} = 0$	$\mathbf{D} = 0$	L = 0
OVER 5	V = 0	D = 0	L = 0
5 AND UNDER	V = U	$\mathbf{D} = 0$	
! OF ! OF ! OF !			
ORDER A ORDER			guit
F1F2F3	F4 F5	5 F6	F7 F8

Step Siz - (continued)

To input the values for CUT. SPEED (SFM) the following steps must be taken. they are :



Normally, the SFM values for threading will all be input as the same value, there is no means of doing a global input, so each value must be entered seperately.

<u>Step Six - (continued)</u>

The cursor must be returned to the top of the CUT. DEPTH columm for entering of the values. This is accomplished by pressing the up cursor in arrow seven times and the right cursor is arrow once. To input the values for CUT. DEPTH the following steps must be taken, they are :



Step Six - (continued)

The cursor must be returned to the top of the FIN. STOCK column for entering of the values. This is accomplished by pressing the up cursor 1 arrow seven times and the right cursor arrow once. To input the values for FIN. STOCK the following steps must be taken, they are :



<u>Step Six</u>

Upon completion of the inputs, from pages 35 - 37, the CRT screen should be as displayed below.

PROG OPERATION IGF - 5 - NO. 1= SS303 THREADS PER INCH	*THREAD CUT. SPEED	MAT. DATA CUTTING* CUT DEPTH	0.0001 in FIN. STOCK
OVER 24 OVER 16 OVER 12 OVER 10 OVER 8 OVER 6 OVER 5 5 AND UNDER	V = 260 V = 260	D = 120 D = 163 D = 189 D = 209 D = 210 D = 233 D = 259 D = 283	$L = 20 \\ L = 20 \\ L = 12 \\ L = 12 \\ L = 12 \\ L = 8 \\$
! OF ! OF ! OF			
order 🛉 order 🚽			guit
F1 F2 F3	F4 F	5 F 6	F7 F8

(38)

Step Seven

At step six we defined values for THREADING to accommodate, constant surface footage, first pass depth of cut and finish stock allowance. To advance the control to the next screen (step seven), we must press p_2 order \downarrow , the CRT screen should be as displayed below.

This screen allows us to input a value for TAPPING, this value is for constant surface footage.

No decimal points are allowed on this page, so a decimal value of .0020, must be input as 20

V = Constant Surface Footage

PROG OPERATION - 6 - NO. 1= 88303	IGF MAT. •TAPPING•	DATA 0.0001 in
CUTTING SPEED	V =	88
2		
! OF ! OF ! OF !		
order 🛉 order 🗼		guit
F1P2I	F3 F4 F5	F6 F7 F8

To input the values for CUTTING SPEED (SFM) the following steps must be taken. they are :



Upon completion of the inputs, from the top of this page, the CRT screen should be as displayed below.



Step Eight

At step seven we defined a value for TAPPING to accommodate, constant surface footage. To advance the control to the next screen (step eight), we must press

F2 $ORDER \downarrow$, the CRT screen should be as displayed below.

This screen allows us to input values for GROOVING, which include values for constant surface footage, feedrates and depths of cut.

No decimal points are allowed on this page, so a decimal value of .0020, must be input as 20

V = Constant Surface Footage

FR = Feedrate (when in cut)

D = Depth of cut per peck (a "D" of .08 equals .040 on a side)



(41)

Step Eight - (continued)

To input the values for the CUT. SPEED (SFM) the following steps must be taken, they are :

TOOL WIDTH



Step Eight - (continued)

The cursor must be returned to the top of the FEEDRATE column for entering of the values. This is accomplished by pressing the up cursor arrow five times and the right cursor arrow once. To input the values for the FEEDRATE (IPR) the following steps must be taken, they are :



<u>Step Eight - (continued)</u>

The cursor must be returned to the top of the CUT. DEPTH columm for entering of the values. This is accomplished by pressing the up cursor arrow arrow five times and the right cursor arrow once.

To input the values for the CUT. DEPTH the following steps must be taken , they are :

TOOL WIDTH



Step Eight

Upon completion of the inputs, from pages 42 - 44, the CRT screen should be as displayed below.

PROG OPERATION - 7 - NO. 1= \$\$303 TOOL WIDTH UNDER 0.125 UNDER 0.189 UNDER 0.312 UNDER 0.472 UNDER 0.787 0.787 AND OVER ! OF ! OF ! OF	IGF CUT. S VR = 2 VR = 2	MA GROOVING* SPEED F 200 FR 230 FR 230 FR 200 FR 165 FR	T. DATA EEDRATE E = 30 E = 40 E = 60 E = 50 E = 30 E = 20	0.000 CUT. D = D = D = D = D = E	DEPTH 600 800 800 1200 1200
order 🛉 order 🚽				guit	
F1 F2 F	F3 F4	F5	F6	F7	F8

.1

Step Nine

At step eight we defined values for GROOVING to accommodate, constant surface footage, feedrate and depth of cut. To advance the control to the next screen (step nine), we must press $\mathbb{F2}$ order \downarrow , the CRT screen should be as displayed below.

This screen allows us to input values for FINISH constant surface footage, X and Z-axis FINISH stock allowance and up to four choices of FINISH feedrate, for GROOVING FINISHING.

> No decimal points are allowed on this page, so a decimal value of .0020, must be input as 20

PROG OPERATION - 8 - NO. 1= \$\$303	IGF *GRO	MAT. DAT	XA 0.000 3*	01 in
CUTTING SPEED FINISHING STOCK FINISHING STOCK FINISH V FINISH VV FINISH VV FINISH VVV	X-AXIS Z-AXIS (ROUGH) FEED (SEMI-FINISH) (FINISH) FEED (FINE FINISH))	RATE FEEDRATE RATE FEEDRATE	VX= LX= LZ= F1= F2= F3= F4=	0 0 0 0 0 0 0
! OF ! OF ! OF !	-			
order 🛉 order ↓			guit	
F1 F2 F	r3 F4	F5 F6	F7	F8

(46)

J

Step Nine - (continued)

To input the values for VF, LX, LZ, F1, F2, F3 and F4, the following steps must be taken, they are :

•

2

Step Nine

Upon completion of the inputs, from page 47, the CRT screen should be as displayed below.

PROG OPERATION - 8 - NO. 1= SS303	IGF MA	AT. DATA 0.0 IISHING*	001 in
CUTTING SPEED FINISHING STOCK FINISHING STOCK FINISH V FINISH VV FINISH VV FINISH VVV	K-AXIS Z-AXIS (ROUGH) FEEDRATE (SEMI-FINISH) FEEDRA (FINISH) FEEDRATE (FINE FINISH) FEEDRA	VX= LX= LZ= F1= ATE F2= F3= TE F4=	330 80 40 120 80 50
! OF ! OF ! OF !			
order 🛉 order ↓		guir	
F1 F2 F	3 F4 F5	F6 F7	F8

Step Ten

At step nine we defined values for GROOVE FINISHING to accommodate,

finish constant surface footage, finish stock allowance and four finish feedrates.

To advance the control to the next screen (step ten), we must press

F2 ORDER

, the CRT screen should be as displayed below.

This screen allows us to input values for DRILLING(HSS), which include values for constant surface footage, feedrate and depth of cut per "peck", all based against the current size drill you need to use.

> No decimal points are allowed on this page, so a decimal value of .0020, must be input as 20

- V = Constant Surface Footage
- F = Feedrate expressed as (IPR)
- **D** = Depth of cut per "peck"

PROG OPERATION IGF MAT. DATA - 9 -0.0001 in NO. 1= SS303 *DRILLING(HSS)* DRILL DIA.(inch) CUT. SPEED FEEDRATE CUT. DEPTH **UNDER 3/16** D = F = 0 0 **UNDER 5/16** V as 0 Fæ 0 $\mathbf{D} =$ 0 **UNDER 9/16** V = 0 $\mathbf{F} =$ 0 D = 0 **UNDER 15/16** V * 0 $\mathbf{F} =$ 0 **D ≡** 0 F = **D** = UNDER 1 5/16 V = 0 0 0 UNDER 1 15/16 V = 0 **D** = F = 0 0 1 15/16 AND OVER V = 0 F = 0 D =0 ! OF ! OF ! OF 1 QUIT order 4 ORDER F1R. . F3 F4 F5F6 **F7 F8**

Step Ten - (continued)

To input the values for CUT. SPEED (SFM) the following steps must be taken, they are :

DRILL DIA.(inch)

1



Step Ten - (continued)

The cursor must be returned to the top of the FEEDRATE column for entering of the values. This is accomplished by pressing the up cursor arrow arrow six times and the right cursor arrow once.

To input the values for FEEDRATE (IPR) the following steps must be taken, they are :

DRILL DIA.(inch)



(51)

Step Ten - (continued)

The cursor must be returned to the top of the CUT. DEPTH columm for entering of the values. This is accomplished by pressing the up cursor arrow arrow arrow once.

To input the values for CUT. DEPTH the following steps must be taken, they are :



<u>Step Ten - (continued)</u>

Upon completion of the inputs, from pages 50 - 52, the CRT screen should be as displayed below.

PROG OPERATION 1 - 9 - NO. 1= \$\$303 DRILL DIA.(inch) UNDER 3/16 UNDER 5/16 UNDER 15/16 UNDER 1 5/16 UNDER 1 15/16 1 15/16 AND OVER ! OF ! OF ! OF	IGF CUT. V = V = V = V = V = V =	DRILLING SPEED 33 33 33 33 33 33 33 33	MAT. DA (HSS)* FEEDRA F = 2 F = 3 F = 4 F = 3 F = 2 F = 2 F =	TA (),0 (),	001 in DEPTH 800 1200 1200 1200 1200
order 🛉 order 🚽				guit	
F1 F2 F3	3 F 4	4) F 5	F	5 F 7	F8

Step Eleven

At step ten we defined values for DRILLING(HSS) to accommodate, constant

surface footage, feedrate and depth of cut per peck, based on the size of drill used.

ORDER

82

To advance the control to the next screen (step eleven), we must press

, the CRT screen should be as displayed below.

This screen allows us to input values for DRILLING(CARBIDE), which include values for constant surface footage, feedrate and depth of cut per "peck", all based against the current size drill you need to use.

> No decimal points are allowed on this page, so a decimal value of .0020, must be input as 20

- V = Constant Surface Footage
- **F** = Feedrate expressed as (IPR)
- **D** = Depth of cut per "peck"



<u>Step Eleven - (continued)</u>

To input the values for CUT. SPEED (SFM) the following steps must be taken, they are :



Step Eleven - (continued)

The cursor must be returned to the top of the FEEDRATE column for entering of the values. This is accomplished by pressing the up cursor arrow four times and the right cursor arrow once.

To input the values for FEEDRATE (IPR) the following steps must be taken, they are :



<u>Step Eleven - (continued)</u>

The cursor must be returned to the top of the CUT. DEPTH column for entering of the values. This is accomplished by pressing the up cursor arrow four times and the right cursor arrow once.

To input the values for CUT. DEPTH the following steps must be taken, they are :



<u>Step Eleven - (continued)</u>

Upon completion of the inputs, from pages 55 - 57, the CRT screen should be as displayed below.

PROG OPERATION IC - 10 - NO. 1= SS303 DRILL DIA.(inch) UNDER 1 3/16 UNDER 1 9/16 UNDER 1 15/16 UNDER 2 3/8 2 3/8 AND OVER ! OF ! OF ! OF	*DRILLING(CA CUT. SPEED FE V = 260 1 V = 260 1	T. DATA 0.0 ARBIDE)* 0.0 DEDRATE CUT. 1 F = 30 D = F = 20 D =	001 in DEPTH 4000 4000 4000 4000
order 🛉 order 🚽		guit	
F1 F2 F3	F4 F5	F6 F7	F8

Step Twelve

At step eleven we defined values for DRILLING(CARBIDE) to accommodate, constan surface footage, feedrate and depth of cut per peck, based on the size of drill used. To advance the control to the next screen (step twelve), we must press ORDEF

, the CRT screen should be as displayed below.

This screen allows us to input values for DRILLING(CENTERING), which include values for revolution per minute (RPM), feedrate and depth of cut per "peck".

No decimal points are allowed on this page, so a decimal value of .0020, must be input as 20

S = Revolution per minute (RPM)

F = Feedrate expressed as (IPR)

D = Depth of cut per "peck"



(59)

÷, †

Step Twelve - (continued)

To input the values for SPINDLE RPM (S), FEEDRATE (F) and DEPTH OF CUT (D), the following steps must be taken, they are :



Upon completion of the inputs, from above on this page, the CRT screen should be as displayed below.



Step Thirteen

At step twelve we defined values for DRILLING(CENTERING) to accommodate, RPM , feedrate and depth of cut per "peck". To advance the control to the next screen (step thirteen), we must press $\mathbb{P2}^{ORDER} \downarrow$, The CRT screen should be as displayed below.

This screen allows us to input values for CENTERING, which include values for revolutions per minute and feedrate.

No decimal points are allowed on this page, so a decimal value of .0020, must be input as 20

S = Revolutions per minute (RPM)

F = Feedrate expressed as (IPR)



Step Thirteen - (continued)

To input the values for SPINDLE RPM (S) and FEEDRATE (F), the following steps must be taken, they are :



Upon completion of the inputs, from above on this page, the CRT screen should be as displayed below.



Step Fourteen

At step thirteen we defined values for CENTERING to accommodate, revolutions per minute (RPM) and feedrate (IPR). To advance the control to the next screen (step fourteen), we must press \mathbb{P}_2 ORDER \downarrow , The CRT screen should be as displayed below.

This screen allows us to input values for RECESSING, which include values for constant surface footage and feedrate.

No decimal points are allowed on this page, so a decimal value of .0020, must be input as 20

V = Constant surface footage (SFM)

F = Feedrate expressed as (IPR)



Step Thirteen - (continued)

To input the values for CONSTANT SURFACE FOOTAGE (V) and FEEDRATE (F), the following steps must be taken, they are :



Upon completion of the inputs, from above on this page, the CRT screen should be as displayed below.



PARAMETER DATA

Parameters are used to establish constant conditions for the OKUMA control. These parameters can include conditions as diverse as cutting tool constant clearance approach points, to setting the minimum and maximum RPM values for each gear range available on your machine tool.

Within the IGF parameters are eleven pages, that will allow you to pre-set the values for a job, or to set values once for conditions that will never change from piece-part run to piece-part run.

The parameter pages are :

PAGE NO.	DESCRIPTION
- 1 -	*DIMENSION PARAMETER*
- 2 -	*INTEGER PARAMETER*
- 3 -	*INTEGER PARAMETER*
- 4 -	*INTEGER PARAMETER*
- 5 -	*PERCENT PARAMETER*
- 6 -	*PERCENT PARAMETER*
- 7 -	*PERCENT PARAMETER*
- 8 -	*SPINDLE ROT* *CONST SPEED* *RETRACT* *APPROACH*
- 9 -	*DRILLING* *GROOVING* *COOLANT*
- 10 -	*BAR FEEDER/BAR PULLER PARAMETER*
- 11 -	*BAR FEEDER/BAR PULLER PARAMETER*

For the next several pages each of these pages will be discussed in great detail, as to HOW the values can be input. WHY they should be input or changed, and WHAT effect the values will have on the machine, or the IGF program. IGF Procedure for Parameter Data Entry :

Step One

From the normal machine operation mode, press the EDIT AUX key then press the function key **P**7, the CRT should display the IGF start-up page.

PI	ROG OPEI	RATION 1	IGF	•			
				л т/			
		Ur		A 10	Ţ		
= IGF							
Key in tl (when u	te file name sing the gra	and press phic edit	the WRIT restart, ke	E key y in '*' as :	a file name))	
GRAPHIC EDIT	PROGRAM MAKE	TOOL DATA	MATE- RIAL	PARA- METER	IGF CONVERT	igf guit	
F1	F2	F3	F4	F5	F6	F 7	F8

At any time the IGF session, for Parameter Data Entry, may be terminated by

pressing function key

F7 · '

. There will be no loss of input data.

Step Two

To access the IGF parameter section press function key



15

below the CRT screen.

The CRT csreen should be as displayed below.



The first parameter page (DIMENSION PARAMETER) contains thirteen parameter lines. As you can see, only twelve are now being used at this time.

Starting on page 68 and continuing for the next several pages, each parameter will be shown graphically as to it's function, and a brief description will be given as to how the value is entered into the control.

Step Two : (continued)

The first three parameters are used to establish rapid clearance points from the piece part geometry. Once established, they are modal for all jobs until you, the programmer need to change them.



Step Two : (continued)

To enter the parameter values for numbers 1, 2 and 3, the following steps must be taken :

Make sure the cursor highlight is at the top of the column, use the cursor keys

up 1 and down	
----------------------	--

to accomplish this task.

Enter the values :



If entered correctly, the CRT screen should be as displayed below.



(69)
Parameters number 4 and 5 are used to establish constant dimensions for length and inside diameter. This is useful if a series of piece parts all have the same length and I/D.



To enter the parameter values for numbers 4 and 5, the following steps must be taken :

Make sure the cursor highlight is located at parameter number 4, use the cursor



Enter the values :





The IGF graphics allows for the moving of program zero from the rear of the part to the front of the part. This is accomplished by using parameters 6 and 7. If you decide to move program zero, remember to change dimension zero also.



EXAMPLE :



(72)

To enter the parameter values for numbers 6 and 7, the following steps must be taken :

Make sure the cursor highlight is located at parameter number 6, use the cursor



Enter the values :





Parameter number 8 allows the IGF function to calculate a distance past the end-point, or to over-travel the last end-point, for cancelling of tool nose radius compensation. With this in effect, cancelling is not done on the piece part.



EXAMPLE :

If PARAMETER No. 8 is left at zero and cutter compensation is used within IGF, the tool will stop at the end point.





To enter the parameter values for number 8, the following steps must be taken : Make sure the cursor highlight is located at parameter number 8, use the cursor



PROG OPERATION IGF	PARAMETER			
- 1 -	1 in			
•DIMENSION PARA	METER*			
1 OD CLEARANCE	0 2000			
2 ID CLEARANCE	0.2000			
3 FACE CLEARANCE	0.1000			
4 BLANK INSIDE LENGTH IL	5.5000			
5 BLANK INSIDE DIA. ID	1.0000			
6 DIMENSION ZERO SHIFT	5.5000			
7 PROGRAM ZERO SHIFT	5.5000			
S NOSE R CANCEL TRAVEL	0:0393			
9 CENTER LENGTH L2	0.0000			
10 CENTER DIA. D2	0.0000			
11 CENTER HOLE DIA, D3	0.0000			
12 GROUVING CLEARANCE	0.0000			
15				
1 5.5				
15.5				
1 .0393				
	OUIT			
	3			
FI FZ F3 F4 F5	FO F 7 F 8			

Parameter numbers 9, 10 and 11 are used to define the length the center is extended from the tailstock (L2), the actual physical diameter of the center (D2), , and the diameter in the part that the center will engage (D3)



To enter the parameter values for numbers 9, 10 and 11, the following steps must be taken :

Make sure the cursor highlight is located at parameter number 9, use the cursor keys up and down to accomplish this task.

Enter the values :



If entered correctly, the CRT screen should be as displayed below.



(77)

As you will see in IGF graphics, grooves wider then the width of the groove tool may be roughed and finished. The parameter number 12 allows a clearance value to be established for the "Z"-axis on the rapid retract move back to the start point. The physical value of this parameter cannot exceed .0390 for the stand-off value.

PROG OPERATION IGF	PARAMETER
DIMENSION PAR	AMETER
1 OD CLEARANCE 2 ID CLEARANCE 3 FACE CLEARANCE 4 BLANK INSIDE LENGTH IL 5 BLANK INSIDE DIA. ID 6 DIMENSION ZERO SHIFT 7 PROGRAM ZERO SHIFT 8 NOSE-R CANCEL TRAVEL 9 CENTER LENGTH L2 10 CENTER DIA. D2 11 CENTER HOLE DIA. D3 12: GROOVING: CLEARANCE::::::::::::::::::::::::::::::::::::	0.2000 0.2000 0.1000 5.5000 5.5000 5.5000 0.1000 2.2000 2.0000 0.3000
.3	
ORDER	gur
F1 F2 F3 F4 F5	F6 F7 F8

EXAMPLE:



Retract



Reposition



Reposition



Feed to Depth



Feed to Depth



Feed Across Face



Retract

To enter the parameter values for number 12, the following steps must be taken : Make sure the cursor highlight is located at parameter number 12, use the cursor

to accomplish this task. keys up and down Enter the values : For parameter number 12 - press and WRITE 5

If entered correctly, the CRT screen should be as displayed below.

PROG OPERATION IGF - 1 - *DIMENSION PAR	PARAMETER 1 in RAMETER*
1 OD CLEARANCE 2 ID CLEARANCE 3 FACE CLEARANCE 4 BLANK INSIDE LENGTH IL 5 BLANK INSIDE DIA. ID 6 DIMENSION ZERO SHIFT 7 PROGRAM ZERO SHIFT 8 NOSE-R CANCEL TRAVEL 9 CENTER LENGTH L2 10 CENTER DIA. D2 11 CENTER HOLE DIA. D3 122 GROOVING CLEARANCE 13 1 .1 1 .005	0.2000 0.2000 0.1000 5.5000 5.5000 0.1000 2.2000 2.0000 0.3000
order 🚽	gur
F1 F2 F3 F4 F5	$ \mathbf{F6} \mathbf{F7} \mathbf{F8} $

(79)

At step two we defined values for the *DIMENSION PARAMETER* page. To advance the control to the next screen (step three), we must press **F2** ORDER , the CRT screen should be as displayed below.

- 2 -	
INTEGER PARAMETER	
9-94 4 600 July 1997 1997 1997 1997 1997 1997 1997 199	
1 SEQUENCE NO. INCREMENTS	
2 MATERIAL CODE DIGITS 0	
3 M41 MINIMUM RPM 0	
4 M42 MINIMUM RPM 0	
5 M43 MINIMUM RPM 0	
6 M44 MINIMUM RPM 0	
7 M41 MAXIMUM RPM 0	
8 M42 MAXIMUM RPM 0	
9 M43 MAXIMUM RPM U	
10 M44 MAXIMUM KPM 0	
11 MAXIMUM SPINDLE RPM U	
12 TOOL DATA BADAMETED O	
15 IOOLDAIA FARAMEIER V	
1.3	
1.005	
1 OF	
1	
gur gur	
FI BOILFS FA FF FF FC F7	20
	, o

The second parameter page (INTEGER PARAMETER) contains thirteen parameter lines.

Starting on page 81 and continuning for the next several pages, each parameter will receive a brief description as to it's function and how to enter it into the control.

The first parameter, number one, allows us to set the sequence number increments This value should normally be entered as "0" (zero) and it will number the IGF output by increments of one starting with sequence number N0001.

If you wish to assign special sequence numbers to each cutting tool, then enter a value starting with "1" (one). The output program will start with N0001 and at the first tool will change to N0010, next (or second) tool will be N0020, and so on to the end of the program.



EXAMPLE :

IF PARAMETER IS " 0 "

IF PARAMETER IS "1"

N0001 G00 X20 Z20 N0002 G50 S3500 N0003 G97 S429 M41 M03 M08 N0004 G00 X3.6 Z0.3 T070707 N0001 G00 X20 Z20 N0002 G50 S3500 N0010 G97 S429 M41 M03 M08 N0011 G00 X3.6 Z0.3 T070707

11

IF PARAMETER IS " 2 "

N0001 G00 X20 Z20 N0002 G50 S3500 N0020 G97 S429 M41 M03 M08 N0021 G00 X3.6 Z0.3 T070707

To enter the parameter values for number 1, the following steps must be taken :

Make sure the cursor highlight is at the top of the column, use the cursor keys





If you turn back to page 25 (**MATERIAL TABLE**), there are thirteen choices for material input. If the normal flow of material, that you must machine, is nearly always the same material and you do not need to identify material every time an IGF session is started, then entering a material value (1 - 13) will insure that the same MATERIAL values be chosen every time.

This also insures that the required spindle speeds (RPM), feeds (IPR), and depths of cut are specified only once, in the MATERIAL section.



(83)

To enter the parameter values for number 2, the following steps must be taken :

Make sure the cursor highlight is located at parameter number 2, use the cursor keys up 1 and down 1 to accomplish this task. Enter the values : For parameter number 2 - press 1 and WRITE



Spindle Revolutions Per Minute (RPM) are calculated by the IGF graphics function. The control will then assign the calculated RPM to a machine gear range. Some OKUMA lathes have two gear ranges and others have up to four gear ranges. The *INTEGER PARAMETER* page provides for both.

Parameters 3, 4, 5 and 6, allows you to specify the MINIMUM spindle RPM for every gear range. If the machine tool we are considering is the OKUMA LB-15, it has two gear ranges, the MINIMUM spindle RPM's are :

> M41 - 70 RPM M42 - 283 RPM

The control can now generate the proper "M" function into the IGF output.



(85)

To enter the parameter values for numbers 3 and 4, the following steps must be taken :

Make sure the cursor highlight is located at parameter number 3, use the cursor







Spindle Revolutions Per Minute (RPM) are calculated by the IGF graphics function. The control will then assign the calculated RPM to a machine gear range. Some OKUMA lathes have two gear ranges and others have up to four gear ranges. The *INTEGER PARAMETER* page provides for both.

Parameters 7, 8, 9 and 10, allows you to specify the MAXIMUM spindle RPM for every gear range. If the machine tool we are considering is the OKUMA LB-15, it has two gear ranges, the MAXIMUM spindle RPM's are:

> M41 - 939 RPM M42 - 3800 RPM

The control can now generate the proper "M" function into the IGF output.



1

To enter the parameter values for numbers 7 and 8, the following steps must

be taken :

Make sure the cursor highlight is located at parameter number 7, use the cursor

keys up



to accomplish this task.

Enter the values :





Spindle speed, on any CNC lathe, is limited by the maximum permissable speed of the power chuck. The effect of centrifugal force on its gripping force, unbalanced condition of the wprkpiece, and so on, can be constrained by programming a G50 code at the start of the program.

By entering a value into parameter number 11, any calculated RPM from the IGF graphic function will be compared with the stored parameter. If that calculated RPM is greater then the parameter RPM, the IGF graphic function will substitute the parameter RPM, or the lower RPM.

The IGF graphics function output will generate a G50 code to control the RPM.

PROG OPERATION IGF		PARAMETER
- 2 -		
•IN	TEGER PARAME	TER"
1 SEQUENCE NO. INCREMENT	s 1	
2 MATERIAL CODE DIGITS	ī	
3 M41 MINIMUM RPM	70	
4 M42 MINIMUM RPM	283	
5 M43 MINIMUM RPM	0	
6 M44 MINIMUM RPM	0	
7 M41 MAXIMUM RPM	939	
8 M42 MAXIMUM RPM	3800	
9 M43 MAXIMUM RPM	0	
10 M44 MAXIMUM RPM	0	
111: MAXIMUM SPINDLE RPM	<u></u>	
12 ORDER PARAMETER	0	
13 TOOL DATA PARAMETER	U	
1 283		
1 939		
1 3800		
	T	
ORDER ORDER		
F1 F2 F3 F4	F5 F6	F7 F8

(89)

To enter the parameter values for number 11, the following steps must be taken :

Make sure the cursor highlight is located at parameter number 11, use the cursor

keys up

and down to accomplish this task.

Enter the values :





As you will see, when we enter the discussion for Graphic Edit Process, there are several pages that will have limited data input. Setting of this parameter allows for "no" automatic advance, once the data has been input, or for automatic advance of the current page upon completion of data input.

If the parameter is entered as -1 then no automatic advance is available and the

soft-keys	FI	ORDER A and	F 2	ORDER	must be used to change the pages.
5010 20,70					go

If. however, the value is input as being between 0 and 10, automatic page advancement will occur. In fact the speed of the screen change will be controled by this parameter.



Input of 5 is 5/100 of a second

To enter the parameter values for number 12, the following steps must be taken :

Make sure the cursor highlight is located at parameter number 12, use the cursor

keys uj	p 1	and down	l) to	accomplish	this	task
---------	-----	----------	---	------	------------	------	------

Enter the values :

For parameter number 12 - press	3 5 and	WRITE
---------------------------------	---------	-------

PROG OPERATION IGF	PARAMETER
- 2 -	
INT	EGER PARAMETER
1 SECTIONOR NO INCORPORATE	
A SEQUENCE NO. INCREMENTS	1
9 MA1 MINIMIM DDM	70
A MAO MINIMUM DDM	283
5 M43 MINIMUM RPM	200
6 M44 MINIMIM RPM	Ö
7 M41 MAXIMUM RPM	939
8 M42 MAXIMUM RPM	3800
9 M43 MAXIMUM RPM	0
10 M44 MAXIMUM RPM	Ō
11 MAXIMUM SPINDLE RPM	3500
12: ORDER PARAMETER	1111111111 5 1
13 TOOL DATA PARAMETER	0
1 3800	
! 3500	
15	
	guit
▼	
\square	\frown
F1 F2 F3 F 4	F5 F6 F6 F7 F8

Prior to defining the part graphically and creating tool motion, in the Graphic Edit Process, you must define the cutting tools to the control. If you glance back to pages 8 - 15, we did a lot of work to capture tooling infromation for one specific cutting tool.

This parameter (number 13) allows us three choices as to how we wish to display the cutting tool information in the Graphic Edit Process. The three choices are, ZERO (0), ONE (1), or TWO (2), their function is :

- O If this parameter is chosen, the identified tooling information is used for the graphic program construction but not displayed for your review.
- 1 If this parameter is chosen, the identified tooling information is used for the graphic program and displayed exactly the way the way it was input and stored using the TOOL DATA TABLE section (see page 15 for an example).
- 2 If this parameter is chosen, the identified tooling information is used for the graphic program and shows the same display as parameter number 1, with one big difference. The data for the cutting tool is left blank and must now be input before you can continue with the graphics program.



(93)

To enter the parameter values for number 13, the following steps must be taken :

Make sure the cursor highlight is located at parameter number 13, use the cursor keys up 1 and down 1 to accomplish this task.

Enter the values :



PROG OPERATION IGF	PARAMETER
- 2 -	
	"INTEGER PARAMETER"
1 SEQUENCE NO. INCRE	MENTS 1
2 MATERIAL CODE DIGI	TS 1
3 M41 MINIMUM RPM	70
4 M42 MINIMUM RPM	283
5 M43 MINIMUM RPM	0
6 M44 MINIMUM RPM	0
7 M41 MAXIMUM RPM	939
8 M42 MAXIMUM RPM	3800
9 M43 MAXIMUM RPM	0
10 M44 MAXIMUM RPM	0
11 MAAIMUM SPINDLE RI	PM 3300
12 ORDER FARAMETER	0 9201-11-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1
[.10.1000,04114,1,000,041	***************************************
1 3500	
1 5	
11	
!	
	дит с
\square	
FI F2 F3	FA F5 F6 F7 F8

At step three we defined values for the *INTEGER PARAMETER* page. To

advance the control to the next screen (step four), we must press

F2 ORDER

, the CRT screen should be as displayed below.

PROG OPERATION IGF	PARAMETER	
- 3 - •INTE	GER PARAMETER*	
14 TPI 15 NO. OF THREAD LEADS 16 NO. OF GROOVES 17 FINISHING FEEDRATE 18 IGF FILE STORAGE 19 THREAD IN FEED PATTERN 20 THREAD CUTTING MODE 21 TOOL OFFSET CANCEL 22 SPACE DELETION 23 COORDINATE AXIS LINE 24 NOMINAL SIZE COMMAND (THE 25 TOOL EDGE DATA CHECK MARG 26 TOOL EDGE DATA CHECK (ANG 15 1 1 OF	CONTRACTOR OF CO	
order A order	QUIT	
F1 F2 F3 F4	F5 F6 F7	F8

The third parameter page (INTEGER PARAMETER) contains thirteen parameter lines.

Starting on page 96 and continuning for the next several pages, each parameter will receive a brief description as to it's function and how to enter it into the control.

As you will remember, from using the threading fixed cycles (G71 AND G72), the lead or pitch can be input using the just the "F" variable input, which is equal to (1 / number of threads per inch) or the same value could be specified by using a combination of "F" and "J" variables. Where "F" has a value of one and "J" is equal to the number of threads per inch.

In the latter case of "F" and "J" we know the control will do the dividing for us or it will calculated the lead.

Parameter number 1 allows the setting of the "J" value to be a constant, and makes good sense if all of your threads per inch are the same.





<u>1.00 - four threads per</u> <u>inch</u> <u>parameter input is 4</u>

To enter the parameter value for number 14, the following steps must be taken :

Make sure the cursor highlight is at the top of the column, use the cursor keys up and down to accomplish this task.

Enter the values :

For parameter number 14 - press 4 and WRITE

PROG OPERATION IGF	PARAMETER
- 3 -	A % 57/17/17/17/17
INTEGER PAR	AMELER
14 TPL	1:1:1:1:1:1:1:4: 4
15 NO. OF THREAD LEADS	0
16 NO. OF GROOVES	0
17 FINISHING FEEDRATE	0
18 IGF FILE STORAGE	0
19 THREAD IN FEED PATTERN	0
20 THREAD CUTTING MODE	0
21 TOOL OFFSET CANCEL	0
22 SPACE DELETION	0
23 COORDINATE AXIS LINE	0
24 NOMINAL SIZE COMMAND (THREADING)	0
25 TOOL EDGE DATA CHECK MARGIN (ANG	LE) O
26 TOOL EDGE DATA CHECK (ANGLE)	0
! 1	
! OF	
14	
<u> </u>	
	GUIT
	\frown
F1 F2 F3 F4 F5	F6 F7 F8

From time to time it is sometimes necessary to machine multiple start threads. These will be threads that have all the same thread lead, root diameter, etc.

Parameter number 15 allows us to set how many multiple thread starts any particular job needs.

As you will see in the graphics section, the threading tool will position to the start point for the first thread and machine that thread to finish depth. The graphics will now show the tool backing up or moving to the right to position itself for the next set of threading passes. It will continue to do this set of motion until the number of multiple starts called for in parameter number 15 is satisfied.

The amount or distance that the tool will back up is exactly equal to the current registered lead or thread pitch.



To enter the parameter value for number 15, the following steps must be taken :

Make sure the cursor highlight is located at parameter number 15, use the cursor keys up 1 and down 1 to accomplish this task. Enter the values : For parameter number 15 - press 2 and WRITE

PROG OPERATION IGF	PARAMETER					
- 3 - *INTEGER PARAMETER*						
14 TPI 4 135:NO. OF THREAD LEADS::::::::::::::::::::::::::::::::::::						
1 4 1 2 1						
order 🛉 order 🗼	дит					
F1 F2 F3 F4	F5 F6 F7 F8					

This parameter (number 16) provides a constant for any piece part that has multiple grooves (I/D or O/D), that are all the same size for depth and are equally spaced one from another. The parameter input is to tell the control how many of these grooves there are total.



EXAMPLE: The parameter number 16 value, for this example would be 3.



(100)

To enter the parameter value for number 16, the following steps must be taken :

Make sure the cursor highlight is located at parameter number 16, use the cursor keys up 1 and down 1 to accomplish this task. Enter the values : For parameter number 16 - press 3 and WRITE

If entered correctly, the CRT screen should be as displayed below.

PROG OPERATION IGF	PARAMETER				
- 3 -					
INTEGER P.	*INTEGER PARAMETER*				
14 TPI	4				
15 NO. OF THREAD LEADS	2				
17 FINISHING FEEDBATE	0				
18 IGF FILE STORAGE	õ				
19 THREAD IN FEED PATTERN	ō				
20 THREAD CUTTING MODE	0				
21 TOOL OFFSET CANCEL 0					
22 SPACE DELETION 0					
23 COORDINATE AXIS LINE 0					
24 NOMINAL SIZE COMMAND (THREADING) 0					
26 TOOL EDGE DATA CHECK (ANGLE) 0					
	-				
14					
<u> </u>	1				
	QUIT				
F1 F2 F3 F4 F5	F6 F7 F8				
	() () () () ()				

(101)

If you remember, back in the MATERIAL DATA section we established finish feedrates for general machining (page 33) and specific feedrates for grooving (page 48). Each consisted of four finish feedrates and they looked like this :

Page 33

	NO.	1=	SS303	*FINISHING*		
	CUTT	INC	SPEED		VF=	700
	FINIS	HIN	ig stoci	K X-AXIS	LX=	100
	FINIS	HI	IG STOCH	Z-AXIS	LZ=	20
	FINIS	H	7	(ROUGH) FEEDRATE	F1=	70
	FINIS	H	v v	(SEMI-FINISH) FEEDRATE	F2=	40
	FINIS	H	~ ~ ~	(FINISH) FEEDRATE	F3=	35
	FINIS	H	~ ~ ~ ~	(FINE FINISH) FEEDRATE	F4=	
Page	<u>: 48</u>					
	NO.	1=	SS303	*GROOVE FINISHING*		
	CUTT	INC	SPEED		VX=	330
	FINIS	HIN	IG STOCH	K X-AXIS	LX=	80
	FINIS	HIN	IG STOCH	Z-AXIS	LZ=	40
	FINIS	H	v	(ROUGH) FEEDRATE	F1=	120
	FINIS	H	~ ~	(SEMI-FINISH) FEEDRATE	F2=	80
	FINIS	H	~ ~ ~	(FINISH) FEEDRATE	F3=	50
	FINIS	H		(FINE FINISH) FEEDRATE	F4=	

If we now select and input a parameter value from (1 - 4), which match up with feedrates (F1 - F4), the control will use that feedrate, when generating a output program from the IGF feature for the finish cutting.



(102)

To enter the parameter value for number 17, the following steps must be taken :

Make sure the cursor highlight is located at parameter number 17, use the cursor keys up 1 and down 1 to accomplish this task. Enter the values :

For parameter number 17 - press (2) and WRITE

- 3 - •INTEGER PARAMETER*					
•INTEGER PARAMETER•					
15 NO. OF THREAD LEADS 2	2				
16 NO. OF GROOVES 3	3				
17: FINISHING FEEDRATE					
18 IGF FILE STORAGE 0					
19 THREAD IN FEED PATTERN 0					
20 THREAD CUTTING MODE 0					
21 TOOL OFFSET CANCEL 0					
22 SPACE DELETION 0					
24 NOMINAL SIZE COMMAND (THREADING) 0					
25 TOOL EDGE DATA CHECK MARGIN (ANGLE) 0					
26 TOOL EDGE DATA CHECK (ANGLE) 0					
ORDER ORDER					
	_				
	,)				
	>				

This parameter (number 18) allows us to create a IGF file, make all the necessary steps within IGF and view our program thru to finish. It (the IGF) can now be forced to automatically save the IGF session, or to ask if we wish to save the program before leaving the IGF session.

This save, no save condition is controlled thru parameter number 18, using one of two parameters.

A parameter input of 0 (zero) will force the control to ask if we wish to save the session (Y/N) Yes or No.

A parameter input of 1 (one) directs the control to automaticaly save the session.



To enter the parameter value for number 18, the following steps must be taken :

Make sure the cursor highlight is located at parameter number 18, use the cursor keys up 1 and down 1 to accomplish this task. Enter the values : For parameter number 18 - press 1 and WRITE

PROG OPERATION IGF	PARAMETER		
- 3 -	ARAMETER.		
14 TPI	4		
15 NO. OF THREAD LEADS	2		
16 NO. OF GROOVES	3		
17 FINISHING FEEDRATE	2		
19 THREAD IN FEED PATTERN	0		
20 THREAD CUTTING MODE 0			
21 TOOL OFFSET CANCEL 0			
22 SPACE DELETION 0			
23 COORDINATE AXIS LINE 0			
24 NOMINAL SIZE COMMAND (THREADING) 0			
25 TOOL EDGE DATA CHECK MARGIN (ANGLE) 0			
20 TOOD EDGE DATA CHECK (ANGLE)	v		
13			
! 2			
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
order 🖣 order 📘	Gou		
Parameter number 19 is used to establish depth of cut, for each pass, for the threading routines. Depth is based on the "D" variable assigned within the IGF graphics section. The IGF output, from this parameter will be a "M" code : M73, M74, or M75

- 73 This input will yield an output of M73 for depth of cut.
 The depth of cut will be calculated as D/2, D/4, D/8, D/8, Etc...
- 74 This input will yield an output of M74 for depth of cut. The depth of cut will be at a constant of "D".
- 75 This input will yield an output of M75 for depth of cut. The depth of cut will be calculated as $\sqrt{2D}$, $\sqrt{3D}$, $\sqrt{4D}$, Etc...



To enter the parameter values for number 19, the following steps must be taken :

Make sure the cursor highlight is located at parameter number 19, use the cursor keys up 1 and down 1 to accomplish this task. Enter the values :

For parameter number 19 - press 7 3 and WRITE

PROG OPERATION IGF	PARAMETER
- 3 - •INTEGER H	ARAMETER•
14 TPI 15 NO. OF THREAD LEADS 16 NO. OF GROOVES 17 FINISHING FEEDRATE 18 IGF FILE STORAGE 19: THREAD IN FEED PATTERN: 20 THREAD CUTTING MODE 21 TOOL OFFSET CANCEL 22 SPACE DELETION 23 COORDINATE AXIS LINE 24 NOMINAL SIZE COMMAND (THREADI 25 TOOL EDGE DATA CHECK MARGIN (A 26 TOOL EDGE DATA CHECK (ANGLE) 1 2 1 1 1 73	4 2 3 2 1 1 1 1 1 1 1 1 1 1 1 7 3 1 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
order A order	guit
F1 F2 F3 F4 F5	F6 F7 F8

Parameter number 20 is used to establish the infeed cutting pattern, for the threading routines. The IGF output, from this parameter will be a "M" code: M32 or M33.



To enter the parameter values for number 20, the following steps must be taken :

Make sure the cursor highlight is located at parameter number 20, use the cursor keys up 1 and down 1 to accomplish this task.

Enter the values :

For parameter number 20 - press 3 3 and WRITE

PROG OPERATION IGF	PARAMETER
- 3 -	
INTEGER PA	RAMETER
14 TPT	4
15 NO. OF THREAD LEADS	2
16 NO. OF GROOVES	3
17 FINISHING FEEDRATE	2
18 IGF FILE STORAGE	1
19 THREAD IN FEED PATTERN	73
20: THREAD CUTTING:MODE	33
21 TOOL OFFSET CANCEL	0
22 SPACE DELETION 0	
23 COORDINATE AXIS LINE 0	
24 NOMINAL SIZE COMMAND (THREADING) 0	
25 TOOL EDGE DATA CHECK MARGIN (AN	(GLE) 0
28 TOOL EDGE DATA CHECK (ANGLE)	0
1 73	
1 33	
	1
	gon
F1 F2 F3 F4 F5	F6 F7 F8

In our normal (longhand) method of programming, we normally do not program a tool offset cancel upon completion of a tool usage, just a rapid move to the tool index position. Parameter number 21 allows to keep this programming style, or to have the IGF output a current cutting tool offset cancel at the rapid move to the index position.



To enter the parameter value for number 21, the following steps must be taken :

Make sure the cursor highlight is located at parameter number 21, use the cursor keys up 1 and down 1 to accomplish this task. Enter the values : For parameter number 21 - press 1 and WRITE

PROG OPERATION IGF	PARAMETER
- 3 -	
INTEGER PAR	RAMETER
14 TPI	4
15 NO. OF THREAD LEADS	2
16 NO. OF GROOVES	3
17 FINISHING FEEDRATE	2
18 IGF FILE STORAGE	1
19 THREAD IN FEED PATTERN	73
20 THREAD CUTTING MODE	33
21: TOOL OFFSET CANCEL	:::::::::::::::::::::::::::::::::::::::
22 SPACE DELETION	0
23 COORDINATE AXIS LINE	0
24 NOMINAL SIZE COMMAND (THREADING	i) O
25 TOOL EDGE DATA CHECK MARGIN (AND	SLE) O
26 TOOL EDGE DATA CHECK (ANGLE)	0
	01777
	gon
	\square \square \square
F1 F2 F3 F4 F5	F6 F7 F8

Output format can be controlled with parameter number 22. The program can be displayed with wide spaces between words using a value of "0" (zero), with no spaces between words using a value of "1" (one), or with one space between words using a value of "2" (two).

With parameter 22 set at "0" (zero):

 N0001 G00 X
 20
 Z
 20

 N0002 G50
 S3500

 N0010 G97
 S 429 M41 M03 M08

 N0011 G00 X
 3.6
 Z
 0.3

With parameter 22 set at "1" (one):

N0001G00X20Z20 N0002G50S3500 N0010G97S429M41M03M08 N0011G00X3.6Z0.3T070707

With parameter 22 set at "2" (two):

N0001 G00 X20 Z20 N0002 G50 S3500 N0010 G97 S429 M41 M03 M08 N0011 G00 X3.6 Z0.3 T0707078



(112)

keys up

To enter the parameter value for number 22, the following steps must be taken :

Make sure the cursor highlight is located at parameter number 22, use the cursor

to accomplish this task.

Enter the values :

For parameter number 22 - press 2 and WRITE

and down

PROG OPERATION IGF	PARAMETER
- 3 -	
INTEGER PA	ARAMETER
14 TPI	4
15 NO. OF THREAD LEADS	2
16 NO. OF GROOVES	3
17 FINISHING FEEDRATE	2.
18 IGF FILE STORAGE	1
19 THREAD IN FEED PATTERN	73
20 THREAD CUTTING MODE	33
21 TOOL OFFSET CANCEL	1
22: SPACE DELETION	2
23 COORDINATE AXIS LINE	0
24 NOMINAL SIZE COMMAND (THREADIN	
25 TOOL EDGE DATA CHECK MARGIN (AF	
26 TOOL EDGE DATA CHECK (ANGLE)	U
1 33	
	9UIT
ORDER TORDER	
FI FO FO FO FA FE	TE TT TO
	FO FI FO

Within IGF are several graphics pages, each of these pages show the part and the "X" and "Z" axis. This parameter (number 23) allows you to fix the coordinate line display for the "X" and "Z" axis to one of seven choices.

With parameter 23 set at "O" (zero) The coordinate lines will be solid.	
With parameter 23 set at "1" (one) The coordinate lines will be dotted.	
With parameter 23 set at "2" (two): The coordinate lines will be short dashes	•
With parameter 23 set at "3" (three): The coordinate lines will be long dashes.	annan Valattiat Giverales Contents Generate
With parameter 23 set at "4" (four): The coordinate lines will be alternate lon and short dashes	g -
With parameter 23 set at "5" (five): The coordinate lines will be alternate one long and two short dashes.	
With parameter 23 set at "6" (six) There will be no coordinate lines displaye	:d.
PROC OPERATION ICF	PARAMETER
FROG OFERATION IGF	
- 3 - •INTEGER PARAMET	ER*
 - 3 - INTEGER PARAMET 14 TPI 15 NO. OF THREAD LEADS 16 NO. OF GROOVES 17 FINISHING FEEDRATE 18 IGF FILE STORAGE 19 THREAD IN FEED PATTERN 20 THREAD CUTTING MODE 21 TOOL OFFSET CANCEL 22 SPACE DELETION 23: COORDINATE AXIS LINE:	ER* 4 2 3 2 1 73 33 1 2 0 0 0 0 0
INTEGER PARAMET -3 - "INTEGER PARAMET 14 TPI 15 NO. OF THREAD LEADS 16 NO. OF GROOVES 17 FINISHING FEEDRATE 18 IGF FILE STORAGE 19 THREAD IN FEED PATTERN 20 THREAD CUTTING MODE 21 TOOL OFFSET CANCEL 22 SPACE DELETION 23 COORDINATE AXIS LINE:	ER* 4 2 3 2 1 73 33 1 201 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0

(114)

To enter the parameter value for number 23, the following steps must be taken :

Make sure the cursor highlight is located at parameter number 23, use the cursor keys up 1 and down 1 to accomplish this task. Enter the values : For parameter number 23 - press (4) and WRITE

PROG OPERATION IGF	PARAMETER
- 3 -	
'INTEGE	R PARAMETER
14 TPI	4
15 NO. OF THREAD LEADS	2
16 NO. OF GROOVES	3
17 FINISHING FEEDRATE	2
18 IGF FILE STORAGE	1
19 THREAD IN FEED PATTERN	73
21 TOOL OFFSET CANCEL	
22 SPACE DELETION	2
23: COORDINATE AXIS LINE	4
24 NOMINAL SIZE COMMAND (THRE	ADING) 0
25 TOOL EDGE DATA CHECK MARGI	N (ANGLE) O
26 TOOL EDGE DATA CHECK (ANGLE) 0
1 4	
1	
	guir
	<u>I</u> /
\square	$\neg \frown \frown \frown$
F1 F2 F3 F4 1	F5 F6 F7 F8

When threading with IGF, the system needs to know if the thread height "H" should be calculated from the piece part diameter or from the thread root diameter. Parameter number 24 allows a choice of "O" (zero) for root diameter and "1" (one) for piece part diameter.

With parameter 24 set at "0" (zero):



With parameter 24 set at "1" (one):





To enter the parameter value for number 24, the following steps must be taken :

Make sure the cursor highlight is located at parameter number 24, use the cursor keys up 1 and down 1 to accomplish this task. Enter the values : For parameter number 24 - press 0 and WRITE

PROG OPERATION IGF	PARAMETER
- 3 -	
INTEGER PARAMI	ETER
14 TPI	4
15 NO. OF THREAD LEADS	2
16 NO. OF GROOVES	3
17 FINISHING FEEDRATE	2
18 IGF FILE STORAGE	1
19 THREAD IN FEED PATTERN	73
20 THREAD CUTTING MODE	33
21 TOOL OFFSET CANCEL	1
22 SPACE DELETION	2
23 COORDINATE AXIS LINE	4
24: NOMINAL: SIZE: COMMAND (THREADING) :	
25 TOOL EDGE DATA CHECK MARGIN (ANGLE)	0
26 TOOL EDGE DATA CHECK (ANGLE)	0
1 2	
14	
10	
	guit
	$\neg \frown \frown$
FI F2 F3 F4 F5 F	6 57 59

As we have seen in the TOOL DATA section, the tool geometry for front clearance and total insert angle can be specified as A1 and A2 (see page 12).

This parameter (number 25) allows us to define any geometry considerations we need to make to the control, reguarding the back-side of the cutting tool geometry (see example sketch below). This parameter also would apply to the front side of the cutting tool. This parameter is referred to as " A3 ", but does not have a call-out on the screen.

The parameter is entered as an angle and can be from 0 - 360 degrees.



To enter the parameter value for number 25, the following steps must be taken :

Make sure the cursor highlight is located at parameter number 25, use the cursor keys up 1 and down 1 to accomplish this task. Enter the values : For parameter number 25 - press 3 and WRITE

PROG OPERATION IGF	PARAMETER
- 3 -	
INTEGER PARAMETH	CR
14 77	4
15 NO. OF THREAD LEADS	2
16 NO. OF GROOVES	3
17 FINISHING FEEDRATE	2
18 IGF FILE STORAGE	ī
19 THREAD IN FEED PATTERN	73
20 THREAD CUTTING MODE	33
21 TOOL OFFSET CANCEL	1
22 SPACE DELETION	2
23 COORDINATE AXIS LINE	4
24 NOMINAL SIZE COMMAND (THREADING)	0
25 TOOL EDGE DATA: CHECK MARGIN: (ANGLE)	1111131
26 TOOL EDGE DATA CHECK (ANGLE)	0 '
ORDER A ORDER	9UIT
FI F2 F3 F4 F5 F6	F7 F9

Parameter number 26 pulls in or makes active the angle specified at parameter number 25. This is done by inputting parameter number 26 as either a "O" (zero) for "off", or a "1" (one) for "on ".

For either of these parameters (25 or 26) to now be in effect for our IGF programming, the next parameter (number 27 on the next page) must also be active.

Parameter number 27 is normally thought of as the check for clearance between the backside of the tool and the tailstock center. It then stands to reason that the geometery checking needed, to insure that cutting motion can not be requested that would " crash " the tool into the piece part and that geometery checking needed to insure that the backside of the tool will not ' crash ' into the tailstock center, are both triggered by the same parameter.

It must be remembered, that inputting values to parameters 25 and 26, does not insure part geometry checking. In fact, failure to input the correct value to parameter number 27 will result in a non-checking of clearance, as geometery is entered at the IGF process. So that, incorrect cutting moves are now incorporated into your tape. Correct entry of parameter number 27 will result in geometry to tool clearance checking and an error message will be delivered as soon as the control detects a " crash " condition.

- 3 - INTEGER PARAMETER* 14 TPI 4 15 NO. OF THREAD LEADS 2 16 NO. OF GROOVES 3 17 FINISHING FEEDRATE 2 18 IGF FILE STORAGE 1 19 THREAD IN FEED PATTERN 73 20 THREAD CUTTING MODE 33 21 TOOL OFFSET CANCEL 1 22 SPACE DELETION 2 23 COORDINATE AXIS LINE 4 24 NOMINAL SIZE COMMAND (THREADING) 0 25 TOOL EDGE DATA CHECK (ANGLE) 3 126: TOOL EDGE DATA CHECK (ANGLE) 3 1 0RDER ORDER 0RDER 9 0	PROG OPERATION IGF	PARAMETER
'INTEGER PARAMETER* 14 TPI 4 15 NO. OF THREAD LEADS 2 16 NO. OF GROOVES 3 17 FINISHING FEEDRATE 2 18 IGF FILE STORAGE 1 19 THREAD IN FEED PATTERN 73 20 THREAD CUTTING MODE 33 21 TOOL OFFSET CANCEL 1 22 SPACE DELETION 2 23 COORDINATE AXIS LINE 4 24 NOMINAL SIZE COMMAND (THREADING) 0 25 TOOL EDGE DATA CHECK (ANGLE) 3 26: TOOL EDGE DATA CHECK (ANGLE) 3 126: TOOL EDGE DATA CHECK (ANGLE) 3 13 1 9UIT	- 3 -	
14 TPI 4 15 NO. OF THREAD LEADS 2 16 NO. OF GROOVES 3 17 FINISHING FEEDRATE 2 18 IGF FILE STORAGE 1 19 THREAD IN FEED PATTERN 73 20 THREAD CUTTING MODE 33 21 TOOL OFFSET CANCEL 1 22 SPACE DELETION 2 23 COORDINATE AXIS LINE 4 24 NOMINAL SIZE COMMAND (THREADING) 0 25 TOOL EDGE DATA CHECK (ANGLE) 3 26: TOOL EDGE DATA CHECK (ANGLE) 3 26: TOOL EDGE DATA CHECK (ANGLE) 3 10 1 3 1 9UIT	'INTEGER I	PARAMETER.
15 NO. OF THREAD LEADS 2 16 NO. OF GROOVES 3 17 FINISHING FEEDRATE 2 18 IGF FILE STORAGE 1 19 THREAD IN FEED PATTERN 73 20 THREAD CUTTING MODE 33 21 TOOL OFFSET CANCEL 1 22 SPACE DELETION 2 23 COORDINATE AXIS LINE 4 24 NOMINAL SIZE COMMAND (THREADING) 0 25 TOOL EDGE DATA CHECK (ANGLE): 3 126: TOOL EDGE DATA CHECK (ANGLE): 1 1 0 1 1 0 1 1 0 1 1 0 1 1 0 1 1 0 1 1 0 1 1 0 0 1 0 0 1 0 0 1 0 0 1 0 0 1 0 0 1 0	14 TPT	4
16 NO. OF GROOVES 3 17 FINISHING FEEDRATE 2 18 IGF FILE STORAGE 1 19 THREAD IN FEED PATTERN 73 20 THREAD CUTTING MODE 33 21 TOOL OFFSET CANCEL 1 22 SPACE DELETION 2 23 COORDINATE AXIS LINE 4 24 NOMINAL SIZE COMMAND (THREADING) 0 25 TOOL EDGE DATA CHECK (ANGLE) 3 126: TOOL EDGE DATA CHECK (ANGLE) 3 1 1 0 1 1 1	15 NO. OF THREAD LEADS	2
17 FINISHING FEEDRATE 2 18 IGF FILE STORAGE 1 19 THREAD IN FEED PATTERN 73 20 THREAD CUTTING MODE 33 21 TOOL OFFSET CANCEL 1 22 SPACE DELETION 2 23 COORDINATE AXIS LINE 4 24 NOMINAL SIZE COMMAND (THREADING) 0 25 TOOL EDGE DATA CHECK (ANGLE) 3 26: TOOL EDGE DATA CHECK (ANGLE): ::::::::::::::::::::::::::::::::::::	16 NO. OF GROOVES	3
18 IGF FILE STORAGE 1 19 THREAD IN FEED PATTERN 73 20 THREAD CUTTING MODE 33 21 TOOL OFFSET CANCEL 1 22 SPACE DELETION 2 23 COORDINATE AXIS LINE 4 24 NOMINAL SIZE COMMAND (THREADING) 0 25 TOOL EDGE DATA CHECK MARGIN (ANGLE) 3 26: TOOL EDGE DATA CHECK: (ANGLE)::::::::::::::::::::::::::::::::::::	17 FINISHING FEEDRATE	2
19 THREAD IN FEED PATTERN 73 20 THREAD CUTTING MODE 33 21 TOOL OFFSET CANCEL 1 22 SPACE DELETION 2 23 COORDINATE AXIS LINE 4 24 NOMINAL SIZE COMMAND (THREADING) 0 25 TOOL EDGE DATA CHECK MARGIN (ANGLE) 3 26: TOOL EDGE DATA CHECK (ANGLE): 1 1 1 0 1 1 1 0 1 1 1 0 1 1 1 0 1 1 1 0 1 1 1 0 1 1 1 1 1 0 1 1 1 0 1 1 1 0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 <td>18 IGF FILE STORAGE</td> <td>ī</td>	18 IGF FILE STORAGE	ī
20 THREAD CUTTING MODE 33 21 TOOL OFFSET CANCEL 1 22 SPACE DELETION 2 23 COORDINATE AXIS LINE 4 24 NOMINAL SIZE COMMAND (THREADING) 0 25 TOOL EDGE DATA CHECK MARGIN (ANGLE) 3 125: TOOL EDGE DATA CHECK: (ANGLE): 1 126: TOOL EDGE DATA CHECK: (ANGLE): 1 14 10 13 1	19 THREAD IN FEED PATTERN	73
21 TOOL OFFSET CANCEL 1 22 SPACE DELETION 2 23 COORDINATE AXIS LINE 4 24 NOMINAL SIZE COMMAND (THREADING) 0 25 TOOL EDGE DATA CHECK MARGIN (ANGLE) 3 26:TOOL EDGE DATA CHECK (ANGLE)	20 THREAD CUTTING MODE	33
22 SPACE DELETION 2 23 COORDINATE AXIS LINE 4 24 NOMINAL SIZE COMMAND (THREADING) 0 25 TOOL EDGE DATA CHECK MARGIN (ANGLE) 3 26: TOOL EDGE DATA CHECK (ANGLE)::::::::::::::::::::::::::::::::::::	21 TOOL OFFSET CANCEL	1
23 COORDINATE AXIS LINE 4 24 NOMINAL SIZE COMMAND (THREADING) 0 25 TOOL EDGE DATA CHECK MARGIN (ANGLE) 3 26:TOOL EDGE DATA CHECK: (ANGLE)::::::::::::::::::::::::::::::::::::	22 SPACE DELETION	2
24 NOMINAL SIZE COMMAND (THREADING) 0 25 TOOL EDGE DATA CHECK MARGIN (ANGLE) 3 26: TOOL EDGE DATA CHECK (ANGLE)	23 COORDINATE AXIS LINE	4
25 TOOL EDGE DATA CHECK MARGIN (ANGLE) 3 26: TOOL EDGE DATA CHECK (ANGLE) : : : : : : : : : : : : : : : : : : :	24 NOMINAL SIZE COMMAND (THREADI	NG) 0
26: TOOL EDGE DATA CHECK (ANGLE): :::::::::::::::::::::::::::::::::::	25 TOOL EDGE DATA CHECK MARGIN (A	NGLE) 3
	26: TOOL EDGE DATA CHECK (ANGLE)	
	14	
	10	
	1 3	
		·····
	ORDER A ORDER	guit
	<u>ii</u>	
	$\frown \frown \frown \frown \frown \frown$	
F1 F2 F3 F4 F5 F6 F7 F8	F1 F2 F3 F4 F5	F6 F7 F8

To enter the parameter value for number 26, the following steps must be taken :

Make sure the cursor highlight is located at parameter number 26, use the cursor keys up 1 and down 1 to accomplish this task. Enter the values :

For parameter number 26 - press 1 and WRITE	er number 26 - press 1 and WRITE
---	------------------------------------

PROG OPERATION IGF	PARAMETER
- 3 -	
INTE	GER PARAMETER
14 TPI	4
15 NO. OF THREAD LEADS	2
16 NO. OF GROOVES	3
17 FINISHING FEEDRATE	2
18 IGF FILE STORAGE	1
19 THREAD IN FEED PATTERN	73
20 THREAD CUTTING MODE	33
21 TOOL OFFSET CANCEL	1
22 SPACE DELETION	2
23 COORDINATE AXIS LINE	4
24 NOMINAL SIZE COMMAND (TH	READING) O
25 TOOL EDGE DATA CHECK MAR	CIN (ANGLE) 3
26: TOOL EDGE DATA CHECK AND	ADE
1.0	
	ошт
	3
F1 F2 F3 F4	F5 F6 F7 F8

At step four we defined values for the *INTEGER PARAMETER* page. To

advance the control to the next screen (step five), we must press



, the CRT screen should be as displayed below.



The fourth parameter page (INTEGER PARAMETER) contains thirteen parameter lines. Parameters 34 - 39 are not currently assigned.

Starting on page 120 and continuning for the next several pages, each parameter will receive a brief description as to it's function and how to enter it into the control.

As mentioned on page 120, this parameter (number 27) has several uses, chief among the uses, is to check for clearance between the backside of the cutting tool and the tailstock center. Shown below is an example of a cutting tool and tailstoc.. live center, that will cause the control to issue an error alarm and cease processing the IGF file. This parameter has two values that can be entered, " 0 " (zero) for " off " and " 1 " (one) for " on ".



(123)

.....

To enter the parameter value for number 27, the following steps must be taken :

Make sure the cursor highlight is located at parameter number 27, use the cursor keys up 1 and down 1 to accomplish this task. Enter the values : For parameter number 27 - press 1 and write



Parameter number 28 is used to check for programmed moves of the cutting tool into jaw defined BARRIER areas. Shown below is an example of a cutting tool and jaws, that will cause the control to issuse an error alarm and cease processing, if the cutting tool is programmed into the jaws while using the IGF file. This parameter has two values that can be entered, "0" (zero) for " off " and "1" (one) for " on ".



To enter the parameter value for number 28, the following steps must be taken :

Make sure the cursor highlight is located at parameter number 28, use the cursor keys up and down to accomplish this task.

Enter the values :

For parameter number 28 - press 1 and WRITE

PROG OPERATION IGF	PARAMETER
- 4 -	VTEGER PARAMETER.
27 TAILSTOCK BARRIER C	K M-CODE OUTPUT 1
28 CHUCK BARRIER CHEC	I-CODE OUTPUT:
29 AUTO COMBINED 4-AX	ROGRAMMING (A+B) 0
30 A/B INTERCHANGEABL	ROGRAM 0
31 TOOL INTERFERENCE	CK M-CODE OUTPUT 0
32 NO. OF V-GROOVES	
34	
35	-
36	
37	
38	
39	
	QUIT
	0
\square	
F1 F2 F3	F5 F6 F7 F8

Parameter number 28 is used to check for programmed moves of the cutting tool into jaw defined BARRIER areas. Shown below is an example of a cutting tool and jaws, that will cause the control to issuse an error alarm and cease processing, if the cutting tool is programmed into the jaws while using the IGF file. This parameter has two values that can be entered. " 0 " (zero) for " off " and " 1 " (one) for " on ".

